

Kansas Department on Aging

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>N087076</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____  B. WING: _____	(X3) DATE SURVEY COMPLETED  <b>01/28/2014</b>
NAME OF PROVIDER OR SUPPLIER  <b>AVITA HEALTH AND REHAB AT REEDS COVE</b>		STREET ADDRESS, CITY, STATE, ZIP CODE <b>2114 N 127TH CT EAST WICHITA, KS 67228</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
S 000	INITIAL COMMENTS  The following citations represent the findings of a health resurvey, non-compliance revisit, and complaint investigation #71552.	S 000		
S1364 SS=D	26-40-305 (3) P E - Electrical requirements  (3) Each electrical circuit to fixed or portable equipment in hydrotherapy units shall have a ground-fault circuit interrupter.  This REQUIREMENT is not met as evidenced by: The facility census totaled 58 residents. Based on observation and interview, the facility failed to maintain the hydroculator (device containing hot water and heat packs) on a ground fault circuit interrupter (GFCI) outlet.  Findings included:  - Observation on 1/15/14 at 1:40 p.m. revealed the hydroculator was located in a locked room in the therapy department and the cord not plugged into a GFCI outlet.  Interview with maintenance staff FF on 1/23/14 at 9:32 a.m. revealed he/she knew the hydroculator had to be behind a locked door and confirmed it was not on a GFCI outlet.  Interview with administrative nursing staff A on 1/23/14 at 8:25 a.m. revealed he/she knew the hydroculator needed to be on a GFCI outlet and reported he/she was surprised it was not.  The facility failed to provide a policy regarding the hydroculator.  The facility failed to ensure the hydroculator	S1364		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Kansas Department on Aging

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>N087076</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____  B. WING: _____		(X3) DATE SURVEY COMPLETED  <b>01/28/2014</b>
NAME OF PROVIDER OR SUPPLIER  <b>AVITA HEALTH AND REHAB AT REEDS COVE</b>			STREET ADDRESS, CITY, STATE, ZIP CODE <b>2114 N 127TH CT EAST WICHITA, KS 67228</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
S1364	Continued From page 1 plugged into a GFCI outlet.	S1364			